

# Jack Sissel Pump Service LLC

P.O. Box 608  
Graton, CA 95444  
707-823-6535  
jacksisselpumpservice@gmail.com  
Lic. # 331736

# Invoice

Date	Invoice #
5/23/2023	18-1863

Bill To
Claus & Carolyn Lund 27880 King Ridge Rd Cazadero, CA 95421

**Total amount due upon completion of work.**

Qty	Item	Description	Rate	Amount
3	Well Test	Site visit for Spring Inspection: 3 hours at \$155/hr  Found there to be two abandoned springs on property. Neither of which were connected to water system. There is no drilled Well on property. There is a concrete 5000 Gallon Storage Tank at top of property next to road that is in good shape and can be used in the future. After talking with Fisch Bros Drilling i recommend drilling a new well. Fisch Bros have drilled in several property's surround this one and have good luck finding water anywhere from 3GPM to 20GPM with a max depth of 360ft. I would call Ed Fisch at Fisch Bros Drilling to start the process of getting a well drilled. It will most likely be about 1yr before they could get to drilling.  Fisch Bros Drilling 707-823-3891	155.00	465.00

Subtotal	\$465.00
Sales Tax (8.5%)	\$0.00
Total	\$465.00
Payments/Credits	\$0.00

<b>Balance Due</b>	<b>\$465.00</b>
--------------------	-----------------